

Deutscher Hängegleiterverband e.V. im DAeC DHV-Technikreferat LBA-anerkannte Prüfstelle für Hängegleiter und Gleitsegel

GS TESTFLUG LTF 2009 GIN_FUSE

Test No 026531-GSTF09-626-Harry

Test date 02.04.2014

Location Achensee / Rofan

Type GIN_Fuse

Test type GS Testflug LTF 2009

Test order Auftrag GS Musterprüfung GIN_Fuse (GIN Gliders INC.)

Customer GIN Gliders INC.

Test standard LTF NFL II-91/09

Test standard 2 EN 926-2:2005

Expert Buntz

Result positive

Billing to: 100%

Technical peculiarities

Datum / Unterschrift (Harry Buntz)

RESULTS

PG test flight (general)	
Take off weight [kg] 220	

Weight limit for certification [kg] 220

Number of pilots 2

test pilot Harry Buntz

Harness type Safari Pilot

Harness category Biplace

Minimum speed [km/h] 24

Trim speed [km/h] 39

Accelerated speed [km/h] 48

Accelerator used? No

Trimms fast

en : Klassifizierung

en: Klassifizierung B

EN: ERGEBNISDETAILS NACH LTF 2009

1 Inflation/take-off		A
	Rising behaviour Smooth, easy and constant rising	

Special take off technique required No

2 Landing	Α
Special landing technique required No	

3 Speeds in straight flight Trim speed more than 30 km/h Yes

Speed range using the controls larger Yes than 10 km/h

28.05.2014 16:29 1 von 4

Minimum speed Less than 25 km/h

4 Control movement		Α
Symmetric control pressure	Increasing	
Symmetric control travel	Greater than 65 cm	
5 Pitch stability exiting accelerated f	light	
5 Fitch stability exiting accelerated i	Not carried out because the glider is not equipped with an	
	accelerator	
6 Pitch stability operating controls d	uring accelerated flight	
	Not carried out because the glider is not equipped with an accelerator	
7 Bell stability and domains		
7 Roll stability and damping Oscillations	Peducina	A
Oscillations	Reducing	
8 Stability in gentle spirals		Α
Tendency to return to straight flight	: Spontaneous exit	
9 Behaviour in a steeply banked turn		Α
Sink rate after two turns	12 m/s to 14 m/s	
10.1 Symmetric front collapse		В
-	Rocking back less than 45°	
-	Spontaneous in 3 s to 5 s	
Dive forward angle on exit		
	Entering a turn of less than 90°	
Cascade occurs	s No	
10.3 Comments from the college in con-	alauska d flimba	
10.2 Symmetric front collapse in acco	Not carried out because the glider is not equipped with an	
	accelerator	
11 Exiting deep stall (parachutal sta	II)	Α
Deep stall achieved	Yes	
Recovery	Spontaneous in less than 3 s	
Dive forward angle on exit	: Dive forward 0° to 30°	
Change of course	Changing course less than 45°	
Cascade occurs	s No	
lan		_
12 High angle of attack recovery	Consideration in Land House 2	A
Cascade occurs	Spontaneous in less than 3 s	
Cascade occurs	, in the state of	
13 Recovery from a developed full st	all	В
Dive forward angle on exit		
	No collapse	
Cascade occurs (other than collapses)	No	
Rocking back	Less than 45°	
Line tension	Most lines tight	
14.1 Asymmetric collapse 45-50%		Α
Change of course until re-inflation	Less than 90°	
Maximum dive forward or roll angle	Dive or roll angle 15° to 45°	
Re-inflation behaviour	Spontaneous re-inflation	
Total change of course	Less than 360°	

2 von 4 28.05.2014 16:29

Collapse on the opposite side occurs	No	
Twist occurs		
Cascade occurs	No	
14.2 Asymmetric collapse 70-75%		ı
Change of course until re-inflation	90° to 180°	
Maximum dive forward or roll angle	Dive or roll angle 15° to 45°	
Re-inflation behaviour	Spontaneous re-inflation	
Total change of course		
Collapse on the opposite side occurs	No	
Twist occurs		
Cascade occurs	No	
14.3 Asymmetric collapse 45-50% in	accelerated flight	
	Not carried out because the glider is not equipped with an accelerator	
14.4 Asymmetric collapse 70-75% in	accelerated flight	
	Not carried out because the glider is not equipped with an accelerator	
15 Directional control with a maintai	ned asymmetric collapse	4
Able to keep course	Yes	
180° turn away from the collapsed side possible in 10 s		
Amount of control range between turn and stall or spin	More than 50 % of the symmetric control travel	
16 Trim speed spin tendency		- 4
Spin occurs	No	
1		
17 Low speed spin tendency		
Spin occurs	No	
18 Recovery from a developed spin		
Spin rotation angle after release	Stone eninning in less than 90°	
Cascade occurs		
19 B-line stall		
Change of course before release	Changing course less than 45°	
Behaviour before release	Remains stable with straight span	
Recovery	Spontaneous in less than 3 s	
Dive forward angle on exit	Dive forward 0° to 30°	
Cascade occurs	No	
20 Big ears		ı
Entry procedure	Dedicated controls	
Behaviour during big ears	Stable flight	
Recovery	Recovery through pilot action in less than a further 3 s	
Dive forward angle on exit	Dive forward 0° to 30°	
21 Big ears in accelerated flight		
Dig care in accerciated ingit		

22 Behaviour exiting a steep spiral Tendency to return to straight flight Spontaneous exit

Not carried out because the glider is not equipped with an accelerator

Α

Turn angle to recover normal flight Less than 720°, spontaneous recovery

28.05.2014 16:29 3 von 4

Sink rate when evaluating spiral 14 stability [m/s]

23 Alternative means of directional control

Α

180° turn achievable in 20 s Yes
Stall or spin occurs No

24 Any other flight procedure and/or configuration described in the user's manual

No other flight procedure or configuration described in the user's $\mbox{\it manual}$

Sprachmodul default

Sprachmodul <u>default constants</u>

Sprachmodul default dhv

Sprachmodul <u>default tmo</u>

Sprachmodul erg_flusi

Sprachmodul tmo pruefungen

Sprachmodul tmo_pruefungentestflug

Sprachmodul tmo_pruefungentestfluggs

Sprachmodul tmo_pruefungentestfluggsltf09

Sprachmodul tmo pruefauftraege

Sprachmodul dhv adressen

Sprachmodul tmo muster

Sprachmodul tmo musterfremd

Sprachmodul tmo pruefungsarten

Sprachmodul dhv adressenperson

Sprachmodul dhv_adressenumsetzung

Sprachmodul <u>dhv adressen constants</u>

4 von 4 28.05.2014 16:29